



USE MINIMAL 2 OF THE MOUNTING POSITIONS (4x M6 SCREWS) WHEN MOUNTING THE BASEPLATE ON YOUR RIG.

Mounting Postions Table		
Mounting positions	+ / -	M6 screws needed
1+2+3	++++	6
1 + 3	+++	4
2+3	++	4
1+2	+	4
2	-	2
1	-	2
3	---	2

THE 235 AND (220) DIMENSIONS ARE THE SAME AS FOR MOUNTING THRUSTMASTER T-LCM AND T3PM PEDAL SETS.